DETAILS OF INSPECTION VIOLATIONS

CRITICAL DESCRIPTION LOCATION REF. POINTS NO. **MAIN GALLEY - HOT LINE** 21 THERE WAS NO AMBIENT TEMPERATURE MEASURING DEVICE IN THE ALTO SHAAM OVEN LOCATED BEHIND THE HOT SERVICE LINE. THERE WAS HASH BROWNS AND PANCAKES LOCATED WITHIN THIS UNIT. NEW TEMPERATURE MEASURING DEVICES HAS BEEN INSTALLED. CORR: **MAIN GALLEY - DISHWASH** 20 0 No THE CUTTING BOARDS WERE SEVERELY PITTED AND SCORED. THE SHIP HAS PROGRAM FOR RESANDING AND THIS IS DONE ONE A REGULAR BASIS. CORR: MAIN GALLEY - COMBI OVEN AREA 0 No CONDENSATE WAS NOTED DRIPPING OFF THE DECKHEAD WITHIN THE HOOD FOR THIS AREA. CORR: THE PERSONNEL THAT WORKING IN THIS AREA HAVE BEEN TRAINED IN PROPER USE OF THE OVEN. MAIN GALLEY GENERAL 21 1 No THERE WERE A NUMBER OF ALTO SHAAM HOT HOLDING OVENS THAT WERE MISSING AMBIENT TEMPERATURE MEASURING DEVICES. NEW TEMPERATURE MEASURING DEVICES HAS BEEN INSTALLED. 5 **MAIN GALLEY - PANTRY** 20 0 No THE SURFACE AREA UNDERNEATH THE BLADE OF THE MEAT SLICKER WAS NOT EASILY CLEANABLE. BETTER CLEANING PROCEDURES HAS BEEN IMPLEMENTED. CORR: **MAIN GALLEY - SOUP AREA** 33 0 No THE HOOD WAS PULLING AWAY FROM THE BULKHEAD. CORR: THIS HAS BEEN WELDED. 7 MAIN GALLEY 16 0 Yes POACHED EGGS WERE FOUND IN AN ICE BATH WELL WITHIN TEMPERATURE. THESE POACHED EGGS NEED TO BE REHEATED SO THAT ALL PARTS OF THE FOOD REACH A TEMPERATURE OF AT LEAST 74°C (165°F) FOR 15 SECONDS. EGGS WILL BE DONE TO ORDER. **VEGETABLE PREPARATION** 38 8 0 No IF THE POTATO PEELERS ARE NOT GOING TO BE USED THEY SHOULD BE REMOVED FROM THIS AREA. THE POTATO PEELERS WILL REMAIN AT THE AREA, DUE TO LATER USE. THEY WILL BE MAINTAINED AND CLEANED. CORR: MAIN GALLEY No SOME OF THE ALTO SHAAM UNITS HAD OPEN SEAMS THAT MAKE CLEANING THESE UNIT DIFFICULT TO CLEAN. THE SEAMS HAS BEEN SEALED. CORR: **BAKERY DECK 4** 20 0 No THERE WAS WATER LOCATED IN THE INSIDE LIP OF THE MIXING COLLAR. CORR: BETTER CLEANING PROCEDURES HAS BEEN IMPLEMENTED. GARDEN CAFÉ BUFFET STARBOARD 19 2 No AN UNCOVERED SLICED MEAT TRAY AND AN UNCOVERED SALAD BOWL WAS PLACED ON THE BUFFET LINE FOR PASSENGER USE. THESE WERE NOT PROTECTED BY A SNEEZE GUARD. ALL DISPLAYED FOOD WILL HAVE PROPER SNEEZ GUARDS. CORR: GARDEN CAFÉ BUFFET STARBOARD 26 0 Yes GREASE RESIDUE WAS NOTED ON THE DEEP FRYER COILS. THIS RESIDUE COULD BE SCRAPED OFF. BETTER CLEANING PROCEDURES HAS BEEN IMPLEMENTED. CORR: GARDEN CAFÉ BUFFET STARBOARD 20 Λ Nο THE COILS ON THE DEEP FRYER HAVE BOLTS WITH EXPOSED THREAD. SLOTTED FASTENERS WERE NOTED ON THE DEEP FRYER AS WELL. THESE FOOD CONTACT SURFACES WERE NOT EASILY CLEANABLE. BOLTS HAS BEEN CUTTED AND SLOTTED FASTENERS HAS BEEN REPLACED.

14 GARDEN CAFÉ BUFFET STARBOARD

THE DECKHEAD IN THE BUFFET AREA WAS SOILED WITH FOOD RESIDUE. STEAM FROM THE BAIN-MARIES WAS CREATING CONDENSATION ON THE DECKHEAD.

CORR: THE PERSONNEL THAT WORKING IN THIS AREA HAVE BEEN TRAINED IN PROPER USE OF THE BAIN MARIE. BETTER CLEANING PROCEDURES HAS BEEN IMMPLEMENTED.

15 GARDEN CAFÉ BUFFET STARBOARD

29 0 Yes

0

No

33

THE HAND WASH STATION IS APPROXIMATELY 35 FT. FROM THE MEAT CARVING STATION.

CORR: THE MEAT CARVING STATION HAS BEEN MOVED WITHIN 25 FEET OF THE HAND WASH STATION.

16 GARDEN CAFÉ BUFFET STARBOARD

21 0 No

THE DECORATIONS OVER THE BUFFET LINE WERE NOT EASILY CLEANABLE. SOME OF THESE WERE HANGING OVER THE SERVING LINE AND COULD CONTAMINATE FOODS DISPLAYED THERE.

CORR: THE DECORATIONS HAS BEEN REMOVED.

Page 2 of 4

NORWEGIAN SKY DETAILS OF INSPECTION VIOLATIONS

NO.	LOCATION	REF.	POINTS	CRITICAL D	ESCRIPTION
17	GARDEN CAFÉ BUFFET STARBOARD	27	0	No	
THE D	ECORATIONS OVER THE BUFFET LINE WERE SOILED.				
CORR:	THE DECORATIONS HAS BEEN REMOVED.				
18	GARDEN CAFÉ GALLEY	22	0	No	
THE FI	NAL RINSE GAUGE ON THE POT WASH MACHINE WAS NOT FUNCTIONING PROF	PERLY DURI	NG ACTIVE US	SE.	
CORR:	THE GAUGE HAS BEEN REPLACED.				
19	BELL BOX 2, DECK 4	20	0	No	
SLIGH	T CORROSION WAS NOTED IN THE DISPENSING ARM OF THE COFFEE URNS AND	ON THE BO	OLT INSIDE OF	THE URN.	
CORR:	NCL DIRECTOR OF PUBLIC HEALT AND QUALITY CONTROL HAS BEEN INFOR	RMED. HE W	ILL INVESTIGA	ATE WITH MANUFA	CTURER.
20	BELL BOX II - DECK 4	20	0	No	
THE TI	HREADS ON THE BOLT INSIDE OF THE COFFEE URN ARE EXPOSED AND ARE NO	OT EASILY C	CLEANABLE.		
CORR:	NCL DIRECTOR OF PUBLIC HEALT AND QUALITY CONTROL HAS BEEN INFOR	RMED. HE W	ILL INVESTIGA	ATE WITH MANUFA	CTURER.
21	POTABLE WATER	06	0	No	
	POTABLE WATER ANALYZER/RECORDER CHARTS AT THE BRIDGE SHOWED FREDS OF 4 HOURS WITH NO EXPLANATION OR CORRECTIVE ACTIONS DOCUMENT		IE RESIDUALS	S BELOW 0.2 PPM F	OR
CORR:	BETTER RECORDING PROCEDURES HAS BEEN IMPLEMENTED.				
22	POTABLE WATER	06	0	No	
	IBER OF ANALYZER/RECORDER CHLORINATION CHARTS AT THE BRIDGE HAD R UCH CHART HAD A RECORDING PERIOD OF 28 HOURS PRIOR TO BEING CHANG		PERIODS IN E	EXCESS OF 24 HO	JRS.
CORR:	BETTER RECORDING PROCEDURES HAS BEEN IMPLEMENTED.				
23	KIDS KORNER CHILDRENS CENTER	41	0	No	
FROM	ORTABLE CHILD SEAT WAS REPORTEDLY NOT USED BY THE CHILDREN IN THE ASSISTING IN THAT AREA OF THE TOILET ROOM. RECOMMEND INSTALLATION NG TOILET SEAT WITH A SIZE FOR SMALL CHILDREN.				
CORR:	NCL DIRECTOR OF PUBLIC HEALTH AND QUALITY CONTROL TO INVESTIGATION	TE.			
24	INTEGRATED PEST MANAGEMENT (IPM)	31	0	Yes	
TO BE	RESSURIZED CONTACT INSECTICIDE (565 PLUS XLO) WHICH HAS BEEN USED IN A RESTRICTED USE PRODUCT. IT IS UNCLEAR WHETHER THIS PRODUCT MEETS ART I CLASSIFICATION OF PESTICIDES. IF IT IS A RESTRICTED-USE PESTICIDE, TI NOT SPECIFY HE HAS BEEN CERTIFIED TO APPLY SUCH PESTICIDES.	S THE REQU	IREMENTS SP	ECIFIED IN 40 CDR	152
CORR:	NCL DIRECTOR OF PUBLIC HEALTH AND QUALITY CONTROL TO INVESTIGAT	TE.			
25	GARDEN CAFÉ - OUTSIDE BUFFET	19	2	No	
	O AND ROLLS WERE PRESENTED TO PASSENGERS ON THE SELF SERVICE BUFF WERE SUBJECT TO CONTAMINATION BY PASSENGERS.	FET OUTSIDE	OF THE SNE	EZE SHIELDS WHE	RE
CORR:	ALL DISPLAYED FOOD WILL HAVE PROPER SNEEZ GUARDS.				
26	GARDEN CAFÉ - DISHWASH	22	0	No	
_	PRAY PATTERN IN THE UPPER ARM FINAL RINSE NOZZLES WAS POOR DURING /ASH MACHINE. NOT ALL DISHWARE PASSING THROUGH THIS CHAMBER WAS	-	-		OR
CORR:	HAS BEEN REPAIRED.				
27	GARDEN CAFÉ - DISHWASH	21	0	No	
_	IBER OF THE LARGER FOOD AND CONDIMENT SERVICE CONTAINERS HAD PEEL ACE WAS DIFFICULT TO CLEAN.	ING EXTER	OR PLASTIC (COATING. THE EXF	OSED
CORR:	WILL BE REPLACED BY A DIFFERENT PRODUCT.				
28	GARDEN CAFÉ - POT WASH	21	0	No	
WERE	RAIDED FLEXIBLE METAL PIPE BENEATH THE 3RD SINK COMPARTMENT WERE D SUBJECT TO SPLASH. THE METAL WAS CORRODING AND SHOULD BE EITHER EAN PRODUCT. Page 3 of 4		-		

CORR; THIS PIPE HAS BEEN CHANGED.

29 COMMENT * 0 No

IN DEVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION, CRITICAL-ITEM DEFICIENCIES (DESIGNATED WITH YES IN CRITICAL COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT, SHOULD INCLUDE STANDARD OPERATING PROCEDURES AND MONITORING PROCEDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.

PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: VSP@CDC.GOV

USE EMAIL MESSAGE SUBJECT LINE: SHIP NAME - CAS - [INSERT INSPECTION DATE] .

Page 4 of 4